



Virgin Islands Shipping Registry

Ritter House, PO Box 4751, Wickham's Cay II, Tortola, British Virgin Islands, VG1110

Tel: +1 284 393 0000

Website: www.bvmaritime.vg

• Duty Officer: +1 284 346 8596

• General Email: vishipping@bvmaritime.vg


NAVIGATIONAL WARNING

NOTICE TO MARINERS No.5 - 2023

OWNERS, MANAGERS, OPERATORS, SKIPPERS, AND MASTERS OF ALL VESSELS OPERATING IN THE GORDA SOUND AREA

REFERENCE: MISSING NORTH CARDINAL MARKER OFF MOSQUITO ROCK

LOCATION: GORDA SOUND APPROACHES, MARKING MOSQUITO ROCK, NORTH OFF MOSQUITO ISLAND AT THE NORTHERN TIP OF COLQUHOUN REEF



The North Cardinal Buoy (Lat:18° 31.084'N – Long: 064° 23.348'W) marking the shallow water and submerged dangers north off Mosquito Rock, is reported MISSING from its charted location.

Mariners should keep well north off Mosquito Rock while approaching the entrance to Gorda Sound especially from the west.

7th December 2023

Mariners should maintain a sharp lookout by all available means exercising caution, particularly in periods of darkness and restricted visibility.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001.

Mr. John Samuel
Director of Shipping
Virgin Islands Shipping Registry
Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110

7th December 2023